



SERVICE INFORMATION LETTER

TO : All
FROM : Russell Goulden
SL : SIL.FDC.AS350.0008 Rev A
SUBJECT : AS350 equipped with STC SR00811SE, SR01049SE
EFFECT : Differential Pressure Switch
DATE : Friday, May 01, 2009

DPS – REFERENCE PORT THREAD SIZE

Dear Customer,

The introduction of NEW vendor DPS switch FDC P/N A486-1 introduced a compatibility issue for existing installations when the DPS is located on the engine side of the firewall ONLY.

The initial issue of this SIL introduced a field fix where customers desired to keep the same mounting configuration. (DPS located on the engine firewall side).

The Field Fix is hereby cancelled and replaced by the introduction of FDC Kit available under P/N 1350K1-1.

The Kit is only required when either

- Changing the old superseded DPS FDC P/N 98505-32210 to the latest style FDC P/N A486-1 with an engine firewall side, mounted DPS.
- Installation of a new system where the early mounting configuration is preferred

The current installation configuration is A486-1 DPS mounted on the Xmsn side of the firewall, or optionally mounted on the engine side with the 1350K1-1 Kit.

Kit P/N 1350K1-1 is procurable from FDC Customer Service

Yours Faithfully,

Russell Goulden
Vice President
Director of Certification