

SERVICE INFORMATION LETTER

TO : All AS350 D Operators
FROM : FDC/aerofilter Engineering
SIL NUMBER : SIL.FDC.AS350.0010
EFFECTIVITY : All AS350 D Helicopters modified IAW STC SR01049SE
FDC System Part Number 1350IN1-9
DATE : Friday, August 01, 2008

NEW INLET PLENUM SEAL

1.0 Background

The existing Inlet Seal on the AS350D versions has a high replacement rate due to seal deterioration. (Ref P/N 1350A12-1 Seal Assembly with P/N 1350P5-103 Seal installed)

A new seal made from a different material and colored Dark Blue is now FAA Approved and is currently being manufactured, and will be available from ~ early September 2008.

This SIL is to advise operators of the upcoming availability of the new seal and to remind operators of the Inspection requirement due IAW the current Instructions Continued Airworthiness.

For customers requiring seals between now and new seal availability FDC will supply an old style free of charge.

FDC/aerofilter recommends inspecting the seal during the BFF Inspection. *Before First Flight of the Day”

2.0 Spare kit availability

New seal available ~ September 2008 from FDC/aerofilter spares.
Use same P/N to order (P/N 1350P5-103).

3.0 Installation Time

Estimated ~ 1.0 man hour (New Seal Installation).

FDC/engineering



Russell Goulden
Certification Manager



SERVICE LETTER – RETURN ADVICE
SIL.FDC.AS350.0010

This is to be completed by the customer and will allow FDC to plan and co ordinate supply of new seals.

TO : FDC Engineering
FROM :
COMPANY :
AIRCRAFT : We have ... AS350D type systems in our fleet.
We will need a total ... new style seals
PHONE : 415 884 0555
FAX : 415 884 0505
EMAIL :
DATE :

This page is to be sent to FDC/aerofilter on completion.

POST TO : FDC Engineering
Filtration Development Company LLC
8 Digital Drive, Suite 104.
Novato, California 94949
EMAIL TO : info@fdcaerofilter.com
FAX : 1-415-884-0505